

P.O. Box 65631 Salt Lake City, Utah 84165

Phone: 801—556-9238
Fax: 801—281-3007
rickb@comrestoration.com



PROJECT:

Union Park Complex Restoration Cottonwood Heights, Utah

COMPLETION DATE:

September 2016

PROPERTY MANAGEMENT COMPANY:

NuTerra Partners
Cottonwood Heights, Utah

Project Overview:

The Union Park Complex restoration project was completed in multiple phases over a 3 year period which included replacement of expansion joints, repairs to post tension cables, installing a traffic bearing membrane to approx.150,000 sq. ft. of concrete surface at UP5 and UP6. The final phase of the project was the repair and coating of 21,000 sq. ft. of the exterior facade on building UP6 and installation of new stairs in the UP6 parking structure.







Damage from Woodpecker

Absence of caulking around windows



Cracks in facade



Patching facade prior to coating

UP6 building showing the contrast in appearance before middle section of facade was completed.

Salt Lake City, Utah 84165

Page 2



Phone: 801-556-9238 Fax: 801-281-3007 rickb@comrestoration.com

P.O. Box 65631



PROJECT:

Union Park Complex Restoration Cottonwood Heights, Utah

COMPLETION DATE:

September 2016

PROPERTY MANAGEMENT COMPANY:

NuTerra Partners Cottonwood Heights, Utah

Project Overview:

The Union Park Complex restoration project was completed in multiple phases over a 3 year period which included replacement of expansion joints, repairs to post tension cables, installing a traffic bearing membrane to approx.150,000 sq. ft. of concrete surface at UP5 and UP6. The final phase of the project was the repair and coating of 21,000 sq. ft. of the exterior facade on building UP6 and installation of new stairs in the UP6 parking structure.



Surface Preparation



Traffic bearing deck coating prior to striping



Installation of new stairs



Detail of stair tread



Damaged expansion joint



New expansion joint



Broken Post Tension Cables



Evidence of Broken PT Cable