

PROJECT PROFILE

PROJECT:

The Weber Center
Ogden, Utah

COMPLETION DATE:

Summer of 2005

PROPERTY MANAGER:

Woodbury Corporation

Facility:

The Weber Center is an office tower with below-grade office space.

Problem:

Water was leaking from the pedestrian area thru the ceiling into the facility's below-grade office space.

Solution:

To fix the leaky areas, CRS removed the sidewalk and failed waterproofing, cleaned the substrate, repaired the voids in the structural concrete, and installed new waterproofing. The repair area was flood tested for water leaks prior to the installation of the new concrete sidewalk. CRS worked with the UDOT, the UTA, and the City of Ogden to manage the traffic control aspects of this project.

TOP: The Weber Center. **CENTER:** Void in structural slab that allowed water to leak into the offices below.
BOTTOM: Waterproofing installation in process.

